

## Short Investigation Bulletin

**DATE:** 20<sup>th</sup> April, 2020

**REPORT #** AO-20-000001

**AIRCRAFT REGISTRATION:** N307WL

**INVESTIGATION STATUS:** Completed

### Summary

Occurrence Bulletins are concise reports that detail the facts surrounding an aviation occurrence, as received in the initial notification and any follow-up enquiries. They provide an opportunity to share safety messages in the absence of a full investigation.

Released as required, the Bulletin provides a summary of the less-complex factual investigation reports conducted by the AAIA. The results, based on information supplied by organizations or individuals involved in the occurrence, detail the facts behind the event, as well as any safety actions undertaken. When applicable, the Bulletin also highlights important Safety Messages for the broader aviation community, drawing on earlier AAIA investigations and research.

### General Details

<b>Date and Time of Occurrence:</b>	25 <sup>th</sup> March, 2020; 8:04 PM		
<b>Location:</b>	Governor's Harbour International Airport, Eleuthera, Bahamas		
<b>Persons on Board:</b>	Crew	2	Passengers 0
<b>Injuries:</b>	Crew Passengers		
<b>Commanders License:</b>	Commercial Pilot		
<b>Occurrence category:</b>	Incident		
<b>Occurrence type:</b>	Fuel		
<b>Investigation status:</b>	Final Report Complete		

### Aircraft Details

<b>Aircraft Type and Registration:</b>	Pilatus PC 12/45; N307WL
<b>Year of Manufacture &amp; Serial #:</b>	2000, 307
<b>Number and Type of Engine(s)</b>	1, Turbo-prop
<b>Type of operation:</b>	Commercial
<b>Information Source:</b>	Field Investigation
<b>Nature of Damage:</b>	None

## Occurrence Summary

---

On the 25<sup>th</sup> March, 2020 at approximately 8:04 PM, a Pilatus PC 12/45 aircraft with United States registration N307WL operated by Republic Airways experienced a fuel pump anomaly while in flight.

The pilot reported that while en route to the Space Coast Regional Airport (KTIX), he observed warning indication regarding the aircraft's fuel pump. The flight had originated in Luis Munoz Marin International Airport (TJSJ), San Juan, Puerto Rico. The pilot made the request through ATC to divert to the Governor's Harbor International Airport (MYEM).

The aircraft landed safely without further incident.

The AAIA conducted a limited scope investigation and no safety recommendations were issued.

---

*This Occurrence Bulletin contains facts which have been determined up to the time of issue. It is published to inform the aviation industry and the public of the general circumstances of accidents and serious incidents and should be regarded as tentative and subject to alteration or correction if additional evidence becomes available.*

*All AAIA investigations are conducted in accordance with Annex 13 to the Convention on International Civil Aviation, and The Aircraft Accident Investigation Authority Act and Regulations. The sole objective of the investigation of an accident or incident under these Regulations is the prevention of future accidents and incidents. It is not the purpose of such an investigation to apportion blame or liability. Accordingly, it is inappropriate that AAIA reports should be used to assign fault or blame or determine liability, since neither the investigation nor the reporting process has been undertaken for that purpose.*