



Tel: (242) 397-5509, 5513, 5514, 5520  
 24 hr. Mobile: (242) 376-1617, (242) 376-8334  
 Fax: (242) 327-2192  
 2<sup>nd</sup> Floor, Manx Corporate Center  
 #45 West Bay Street  
 P. O. Box CB-11702  
 Nassau, N. P., Bahamas  
 Website: [www.baaaid.org](http://www.baaaid.org)  
 Email: [baaid@bahamas.gov.bs](mailto:baaid@bahamas.gov.bs)

The following Safety Recommendations were issued as a result of the AAIA Aviation Accident Report derived from investigation file number A18-00009. This accident occurred 5th June 2018 at approximately 3:45 PM, and involved a Cessna 421B aircraft which lost control and crashed shortly after takeoff from the Rocksound Int'l Airport, Rocksound, Eleuthera, Bahamas. The pilot and 2 passengers were killed. Safety recommendations were issued on 6<sup>th</sup> February 2019 and final report published on April 8<sup>th</sup> 2019.

Safety Recommendation Number	Safety Recommendation Recipient	Safety Recommendation Text
SI-18-00030	Bahamas Civil Aviation Authority (BCAA)	1. Recommends the BCAA ensure follow-up surveillance is conducted of the Rock Sound Int'l Airport to verify the findings uncovered have been addressed.
SI-18-00030	Bahamas Civil Aviation Authority (BCAA)	2. It is recommended that the BCAA conduct initial and follow-up inspections of all other airports under their surveillance obligation in a structured and timely manner to ensure their compliance to requirements of the CAGR and international standards as applicable. Inspections should verify that; <ul style="list-style-type: none"> <li>• Where applicable, adequate firefighting equipment are available and functioning.</li> <li>• Adequate personnel are available to accomplish firefighting/crash and rescue obligations (if applicable).</li> <li>• Personnel assigned to firefighting / crash and rescue tasks are qualified and current in their firefighting / crash and rescue tasks (as applicable).</li> <li>• Records are available reflecting qualification and currency of firefighting / crash and rescue personnel (if applicable).</li> <li>• Proper runway and taxiway markings are installed at airports under their surveillance responsibility.</li> </ul>



Tel: (242) 397-5509, 5513, 5514, 5520  
 24 hr. Mobile: (242) 376-1617, (242) 376-8334  
 Fax: (242) 327-2192  
 2<sup>nd</sup> Floor, Manx Corporate Center  
 #45 West Bay Street  
 P. O. Box CB-11702  
 Nassau, N. P., Bahamas  
 Website: [www.baaaid.org](http://www.baaaid.org)  
 Email: [baaid@bahamas.gov.bs](mailto:baaid@bahamas.gov.bs)

SI-18-00035	Airport Authority (AA)	Ensure adequate crash and rescue personnel are available during periods the airport is officially noted as open to the public.
SI-18-00036	Airport Authority (AA)	Ensure personnel at this and all airports under its control, are provided initial and recurrent training relative to the crash and rescue and firefighting tasks they are mandated to perform.
SI-18-00037	Airport Authority (AA)	Coordinate with the relevant authority to ensure proper markings are in place where required on the airport surfaces.
SI-18-00038	Airport Authority (AA)	Ensure adequate equipment is available to transport the fire-extinguishing bottles from their location at the ramp to any position on the airfield, should they be needed.
SI-18-00039	Airport Authority (AA)	Conduct a survey of the airfield and coordinate with other government agencies, as applicable, to correct drainage and eroded surfaces of the runway and taxiways.
SI-18-00040	Ministry of Tourism & Aviation	Recommends the Government of the Bahamas explore ways to find the funding to ensure that suitable crash and rescue, fire-fighting equipment representative of the size of aircraft these airports accommodate be made available.