



Tel: (242) 397-5509, 5513, 5514, 5520  
 24 hr. Mobile: (242) 376-1617, (242) 376-8334  
 Fax: (242) 327-2192  
 2<sup>nd</sup> Floor, Manx Corporate Center  
 #45 West Bay Street  
 P. O. Box CB-11702  
 Nassau, N. P., Bahamas  
 Website: www.aaaid.org  
 Email: [baaid@bahamas.gov.bs](mailto:baaid@bahamas.gov.bs)

## AVIATION OCCURRENCE BULLETIN

**DATE: 20<sup>TH</sup> AUGUST, 2019**  
**REPORT # AO-19-000013**  
**AIRCRAFT REGISTRATION: N6898H**  
**INVESTIGATION STATUS: COMPLETE**

### SUMMARY

Occurrence Bulletins are concise reports that detail the facts surrounding an aviation occurrence, as received in the initial notification and any follow-up enquiries. They provide an opportunity to share safety messages in the absence of a full investigation.

Released as required, the Bulletin provides a summary of the less-complex factual investigation reports conducted by the AAID. The results, based on information supplied by organizations or individuals involved in the occurrence, detail the facts behind the event, as well as any safety actions undertaken. When applicable, the Bulletin also highlights important Safety Messages for the broader aviation community, drawing on earlier AAID investigations and research.

### GENERAL DETAILS

|                                     |                                      |      |                 |
|-------------------------------------|--------------------------------------|------|-----------------|
| <b>Date and Time of Occurrence:</b> | 4 <sup>th</sup> April, 2019          |      |                 |
| <b>Location</b>                     | Marsh Harbour International, Bahamas |      |                 |
| <b>Persons on Board</b>             | Crew                                 | 1    | Passengers 1    |
| <b>Injuries:</b>                    | Crew                                 | None | Passengers None |
| <b>Commanders License:</b>          | Student                              |      |                 |
| <b>Occurrence category:</b>         | Abnormal Runway Contact              |      |                 |
| <b>Occurrence type:</b>             | Incident                             |      |                 |
| <b>Investigation status:</b>        | Final Report Complete                |      |                 |

### AIRCRAFT DETAILS

| Aircraft details                           |                            |
|--|----------------------------|
| <b>Aircraft Type and Registration:</b>     | Cessna 172M                |
| <b>Year of Manufacture &amp; Serial #:</b> | 17265636                   |
| <b>Number and Type of Engine(s)</b>        | Lycoming O-320             |
| <b>Type of operation:</b>                  | General Aviation (trainee) |
| <b>Information Source:</b>                 | AAID Field Investigation   |
| <b>Nature of Damage:</b>                   | None                       |

## Occurrence Summary:

On the 4<sup>th</sup> April 2019, at approximately 12:28 PM LCL, a Cessna 172M aircraft, registration N6898H contacted the runway faster than expected at Marsh Harbour International Airport, Abaco, Bahamas. The pilot acknowledged that the airspeed was high resulting in the aircraft bouncing on landing.

No injuries were reported. No damage occurred. A limited scope investigation was conducted, no safety message(s) or recommendation(s) were issued.

---

*This Occurrence Bulletin contains facts which have been determined up to the time of issue. It is published to inform the aviation industry and the public of the general circumstances of accidents and serious incidents and should be regarded as tentative and subject to alteration or correction if additional evidence becomes available.*

*All AAID investigations are conducted in accordance with Annex 13 to the ICAO Convention on International Civil Aviation, and The Civil Aviation (Investigation of Air Accidents and Incidents) Regulations 2017. The sole objective of the investigation of an accident or incident under these Regulations is the prevention of future accidents and incidents. It is not the purpose of such an investigation to apportion blame or liability. Accordingly, it is inappropriate that AAID reports should be used to assign fault or blame or determine liability, since neither the investigation nor the reporting process has been undertaken for that purpose.*

---