



Tel: (242) 397-5509, 5513, 5514, 5520
 24 hr. Mobile: (242) 376-1617, (242) 376-8334
 Fax: (242) 327-2192
 2nd Floor, Manx Corporate Center
 #45 West Bay Street
 P. O. Box CB-11702
 Nassau, N. P., Bahamas
 Website: www.aaaid.org
 Email: baaid@bahamas.gov.bs

AVIATION OCCURRENCE BULLETIN

DATE: 20TH AUGUST 2019
REPORT # AO-18-000015
AIRCRAFT REGISTRATION: N4432B
INVESTIGATION STATUS: COMPLETED

SUMMARY

Occurrence Bulletins are concise reports that detail the facts surrounding an aviation occurrence, as received in the initial notification and any follow-up enquiries. They provide an opportunity to share safety messages in the absence of a full investigation.

Released as required, the Bulletin provides a summary of the less-complex factual investigation reports conducted by the AAID. The results, based on information supplied by organizations or individuals involved in the occurrence, detail the facts behind the event, as well as any safety actions undertaken. When applicable, the Bulletin also highlights important Safety Messages for the broader aviation community, drawing on earlier AAID investigations and research.

GENERAL DETAILS

Date and Time of Occurrence:	3 rd July, 2018, 10:00 AM		
Location	Lynden Pindling International (MYNN), Nassau, Bahamas		
Persons on Board	Crew	1	Passengers 1
Injuries:	Crew	None	Passengers None
Commanders License:	Airline Transport Pilot		
Occurrence category:	Incident		
Occurrence type:	System Component Failure (Non-Powerplant)		
Investigation status:	Final Report Complete		

AIRCRAFT DETAILS

Aircraft details	
Aircraft Type and Registration:	Piper PA-32RT-300T, N4432B
Year of Manufacture & Serial #:	#32R-7887174
Number and Type of Engine(s)	One, Lycoming TIO-540
Type of operation:	Private
Information Source:	AAID Field Investigation
Nature of Damage:	Damages to nose gear, nose cone, undercarriage.

Occurrence Summary:

On the 3rd July 2018 at approximately 10:00 AM LCL, Piper N4432B was involved in an occurrence at the Lynden Pindling International Airport (MYNN). The aircraft departed from San Salvador International Airport (MYSM) with two souls on board.

The pilot stated that during aircraft landing and roll-out, there was a collapse of the nose gear that resulted in the aircraft being disabled on the runway. The aircraft received damages, there were no injuries reported.

Weather was not a factor in this accident. A limited scope investigation was conducted, no safety message or recommendations were issued.

This Occurrence Bulletin contains facts which have been determined up to the time of issue. It is published to inform the aviation industry and the public of the general circumstances of accidents and serious incidents and should be regarded as tentative and subject to alteration or correction if additional evidence becomes available.

All AAID investigations are conducted in accordance with Annex 13 to the ICAO Convention on International Civil Aviation, and The Civil Aviation (Investigation of Air Accidents and Incidents) Regulations 2017. The sole objective of the investigation of an accident or incident under these Regulations is the prevention of future accidents and incidents. It is not the purpose of such an investigation to apportion blame or liability. Accordingly, it is inappropriate that AAID reports should be used to assign fault or blame or determine liability, since neither the investigation nor the reporting process has been undertaken for that purpose.
