



AVIATION SHORT INVESTIGATION BULLETIN

REPORT # AO-15-005502 INVESTIGATION TITLE: C6-TAK ACCIDENT INVESTIGATION STATUS: COMPLETED

SUMMARY

The Aviation Short Investigation Bulletin covers a range of the AAID's short investigations and highlights valuable safety lessons for pilots, operators and safety managers.

Released as required, the Bulletin provides a summary of the less-complex factual investigation reports conducted by the AAID. The results, based on information supplied by organizations or individuals involved in the occurrence, detail the facts behind the event, as well as any safety actions undertaken. The Bulletin also highlights important Safety Messages for the broader aviation community, drawing on earlier AAID investigations and research.

GENERAL DETAILS

General details			
Date:	21 st November 2017	Investigation status:	Completed
Time:	1730 UTC	Investigation type:	Accident Investigation
Location (<u>show map</u>):	Guatemala City	Occurrence type:	Engine Failure
State:	Guatemala		
Release date:	15 th June 2017	Occurrence category:	Accident
Report status:	Final	Highest injury level:	Minor

AIRCRAFT DETAILS

	Aircraft details
Aircraft manufacturer:	Piper
Aircraft model:	PA-31
Aircraft registration:	С6-ТАК
Serial number:	31-228
Type of operation:	General Aviation
Sector:	Piston
Damage to aircraft:	Destroyed

On 21st November 2015 at approximately 1730 (UTC), C6-TAK was involved in an accident at the La Aurora International Airport Guatemala.

The aircraft had recently undergone maintenance and a test flight was being conducted by the two pilots on board. During the test flight, the pilots experienced a loss of engine power after takeoff that resulted in the aircraft crashing and the two souls on board receiving minor injuries.

The aircraft was completely destroyed as a result of flames that engulfed the plane in the aftermath of the crash.

Please Be Advised That This Case Is Now Closed