



Tel: (242) 397-5509, 5513, 5514, 5520  
24 hr. Mobile: (242) 376-1617, (242) 376-8334  
Fax: (242) 327-2192  
2<sup>nd</sup> Floor, Manx Corporate Center  
#45 West Bay Street  
P. O. Box CB-11702  
Nassau, N. P., Bahamas  
Website: [www.baaid.org](http://www.baaid.org)  
Email: [baaid@bahamas.gov.bs](mailto:baaid@bahamas.gov.bs)

---

## Short Investigation Bulletin

**DATE:** 9<sup>th</sup> February, 2021  
**REPORT #** AO-20-000272  
**AIRCRAFT REGISTRATION:** N4141R  
**INVESTIGATION STATUS:** Completed

### Summary

Occurrence Bulletins are concise reports that detail the facts surrounding an aviation occurrence, as received in the initial notification and any follow-up enquiries. They provide an opportunity to share safety messages in the absence of a full investigation.

Released as required, the Bulletin provides a summary of the less-complex factual investigation reports conducted by the AAIA. The results, based on information supplied by organizations or individuals involved in the occurrence, detail the facts behind the event, as well as any safety actions undertaken. When applicable, the Bulletin also highlights important Safety Messages for the broader aviation community, drawing on earlier AAIA investigations and research.

### General Details

<b>Date and Time of Occurrence:</b>	17 <sup>th</sup> July, 2020; 2:40 PM		
<b>Location</b>	North Eleuthera Airport, Eleuthera, Bahamas		
<b>Persons on Board</b>	<b>Crew</b>	1	<b>Passengers</b> 0
<b>Injuries:</b>	<b>Crew</b>	0	<b>Passengers</b> 0
<b>Commanders License:</b>	Airline Transport Pilot		
<b>Occurrence category:</b>	Incident		
<b>Occurrence type:</b>	Runway Excursion		
<b>Investigation status:</b>	Final Report Complete		

### Aircraft Details

<b>Aircraft Type and Registration:</b>	Piper Cherokee Six (PA-32-300); N4141R
<b>Year of Manufacture &amp; Serial #:</b>	1968; 32-40460
<b>Number and Type of Engine(s)</b>	One; Lycoming
<b>Type of operation:</b>	Private
<b>Information Source:</b>	Field Investigation
<b>Nature of Damage:</b>	Blown tire on right main landing gear

## Occurrence Summary

---

On the 17<sup>th</sup> July, 2020 at approximately 2:40 PM, a Piper Cherokee Six (PA-32-300) aircraft, United States registration N4141R, was involved in an occurrence while landing at the North Eleuthera Airport (MYEH), North Eleuthera, Bahamas.

The pilot reported that while landing at MYEH, the aircraft experienced a blown tire on the right main gear which resulted in a runway excursion. The aircraft eventually came to a rest near the edge of the runway.

There were no safety recommendations issued as a result of this investigation.



*This Occurrence Bulletin contains facts which have been determined up to the time of issue. It is published to inform the aviation industry and the public of the general circumstances of accidents and serious incidents and should be regarded as tentative and subject to alteration or correction if additional evidence becomes available.*

*All AAIA investigations are conducted in accordance with Annex 13 to the Convention on International Civil Aviation, and The Aircraft Accident Investigation Authority Act and Regulations. The sole objective of the investigation of an accident or incident under these Regulations is the prevention of future accidents and incidents. It is not the purpose of such an investigation to apportion blame or liability. Accordingly, it is inappropriate that AAIA reports should be used to assign fault or blame or determine liability, since neither the investigation nor the reporting process has been undertaken for that purpose.*